

## Time in instrument cluster and on analog clock changes continuously and at random

---

|                   |                                                                                    |
|-------------------|------------------------------------------------------------------------------------|
| Topic number      | LI54.30-P-067251                                                                   |
| Version           | 3                                                                                  |
| Function group    | 54.30 Instrument cluster, display instruments, hazard warning device               |
| Date              | 04-04-2018                                                                         |
| Validity          | Model series 213/238 with code 464 up to and including production date, March 2017 |
| Reason for change | Cause, remedy, AN and validity adapted.                                            |
| Reason for block  |                                                                                    |

---

### Complaint:

The time in the instrument cluster and on the analog clock changes continuously and at random. The clock in the display shows the correct time. See Attachment A.

| Attachments |             |
|-------------|-------------|
| File        | Description |
| A.mp4       | A           |

### Cause:

Damaged processor in the IC through electrostatic discharge in production process.

### Remedy:

Please replace the instrument cluster.

| Symptoms                                                                                                                  |
|---------------------------------------------------------------------------------------------------------------------------|
| Communication/information / Information display / Displays / Clock / Malfunction                                          |
| Communication/information / Information display / Displays / Clock / Too fast                                             |
| Communication/information / Information display / Displays / Clock / Too slow                                             |
| Communication/information / Information display / Displays / Clock / Synchronization with navigation system nonfunctional |
| Communication/information / Information display / Displays / Clock / Remains stationary                                   |

| Control unit/fault code              |            |            |
|--------------------------------------|------------|------------|
| Control unit                         | Fault code | Fault text |
| A1 - Instrument cluster (IC) (IC213) | -          | -          |

# XENTRY TIPS

---

| Operation numbers/damage codes |                |      |             |                                        |
|--------------------------------|----------------|------|-------------|----------------------------------------|
| Op. no.                        | Operation text | Time | Damage code | Note                                   |
|                                |                |      | 5440T 50    | Cockpit clock shows incorrect readings |

| WIS-References    |                                   |                                                                            |            |
|-------------------|-----------------------------------|----------------------------------------------------------------------------|------------|
| Document number   | Title                             | Note                                                                       | Allocation |
| AR54.30-P-6015LWE | Remove/install instrument cluster | Valid for vehicles up to production year 2016!<br>Validity: Model 213, 238 | Remedy     |