

ESP OFF button inoperative

Topic number	LI42.47-P-068025
Version	1
Function group	42.47 Adaptive Brake (ABR)
Date	04-19-2018
Validity	Model series 213 AMG Sport (E43 AMG Sport)
Reason for change	
Reason for block	

Complaint:

The ESP OFF button is inoperative.

Additionally, it may not be possible to select drive programs.

Note:

There is no code (DTC) present in the ESP control unit (N30/4).

Cause:

Possibly software of the AMG Drive Unit control unit ((AMG DRVU)(N145/1)).

Remedy:

Update software of AMG Drive Unit control unit and then encode SCN.

Symptoms
Chassis/suspension / Brake system / Brakes/traction regulation system / Electronic Stability Program (ESP) / Malfunction

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			5440Z 90	