

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2018090002, September 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Models CLS-Class and E-Class (257 and 213 platform)**
Model years 2018 and 2019
Replace all wheel bolts

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY18-19 CLS-Class and E-Class (257 and 213 platform) vehicles, the wheel bolts may not meet production specifications, which could result in damage to the bolt heads after repeated installation and removal of the bolts. An authorized Mercedes-Benz dealer will replace the wheel bolts for the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 648 vehicles are affected.

Order No. P-SC-2018090002

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

1. Replace all wheel bolts.



For basic data, see **AR40.10-P-1102A**.



It is not necessary to remove the wheel and tire assemblies from the vehicle.



To ensure the old wheel bolts are not re-used, please damage the threads and dispose.

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
20	Ball seat bolt	A 000 990 76 07	100%

Warranty Information

Operation: Replace all wheel bolts (02-2372)

Damage Code	Operation Number	Labor Time (hrs.)
40 910 39 7	02-2372	0.4



Note

Operation Number labor times are subject to change.