



Technical Tip

Topic	01-18-09TT – DTC U029E00 Lost Communication With NOx Sensor "B" after 23Y8 Campaign is Performed
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	July 20, 2018

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

DTC U029E00 Lost Communication With NOx Sensor "B" after 23Y8 Campaign is Performed

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf, Jetta, Passat, Golf Sportwagen, Beetle, Beetle Convertible	2015	2.0L TDI (CVCA, CRUA)	All	All	All

Technical Background

N/A.

Service

When performing the 23Y8 Campaign, if fault U029E is found, check for swapped connectors at front Nox sensor and harness adapter. Correct installation as needed. Check rear Nox sensor connector to ensure connector is fully seated.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2051936/1	7/20/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.