



Volkswagen

Service Information

Offboard Diagnostic Information System Service (ODIS Service)

Number: VOS-18-18

Subject: Software Version Update, Enhancements and Fixes

Date: Sept. 27, 2018

Supersedes VOS-18-17 due to new Diagnostic Content Version

The following ODIS Service software versions are available for download.

Current ODIS Service Software Versions	
Application: V4.4.10	Diagnostic Content: V2.36.7

Fixes & Enhancements – Highlights:

16 - Jetta 2011 > only USA / Canada. CNLA 1.4I TFSI Hybrid / 110kW:

No test available for airbag DTC B11B311: Igniter for high voltage battery interrupt Short circuit to ground.

CA - Atlas USA/CAN >:

- Remote control key test SYS_X_J519_1_0412_11_Schluessel_pruef_BCM_UDS_00011 should display the current key measured value to make sure it is the same key that set the low battery fault code. This guarantees the replacement of the correct remote key battery that set a fault code.
- Control module communication error message displayed during vehicle systems test: A5 - MQB_B_MFK -EV_MFKBoschMQBB - 001001 the application could not find any diagnostic data that matched exactly.
- R242 00A5 calibration- R242_X_1_0914_11_Kalibrierung_Frontkamera_MFK2_00000 fails due to no communication with the front camera system.

5N - Tiguan 2008 > only USA/Canada:

A/C cooling performance test SYS87_5N_____2_0609_11_kaelteleistung_pruefen_00011 states that "Compressor active, no shut-off condition is present" and still the test ends with instruction to "Repair cause of shut-off requirement..."

Misc. general translation errors.

To identify versions currently installed on a diagnostic device, please refer to **ODIS Service – Service Information** document title: **Online Update Guide – Section 4.0**