

SS 1033743: M2 Parameters Disabled after Programming the BHM

Applicable Vehicles:

All M2 Vehicles

Symptoms:

After programming the bulkhead module (BHM), some M2 vehicles may exhibit altered or disabled functionality with features that were enabled by the following parameters:

26-01001-XXX Charge indicator lamp (related settings)

26-01002-XXX Fuel/Water separator (related settings)

26-01032-XXX PTO air control (related settings)

26-20100-XXX SmartPlex switch 1 (related settings)

Issue:

BHM programming is causing features enabled by these parameters to be disabled.

NOTE: This issue does not affect the functionality of vehicles already in the field, unless they come to a service center for BHM programming.

Solution:

If any of these parameters were enabled on a vehicle, or a fleet of vehicles, contact the Dealer Help Desk with the VIN and the suspected missing parameters.

If any additional parameters are disabled and possibly affected by BHM programming, the Dealer Help Desk can assist in restoring them.

Contact: Dealer Help Desk

URL: <https://dtnacontent-dtna.prp.freightliner.com/content/dtna-connect/it/ITSupport.html>

Phone: (855)639-8680

Email: dealer.helpdesk@daimler.com