

1 08 05-18



## Service Information Bulletin

SUBJECT	DATE
SPN 521049 (TCM)	August 2018

### Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0140	DT12	SPN 521049/FMI 7	This is a new procedure.

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001  
 Telephone: 313-592-5000  
[www.demanddetroit.com](http://www.demanddetroit.com)

## **2 SPN 521049/FMI 7**

### Split Pin Sticking in the Retracted Position

This fault indicates that the TCM detected a stuck/binding split pin during a shift request. Perform the split pin bushing repair. Refer to section "Split Rod Bushing Repair".