

SS: 1033843 TBB Braun Lift too close to the Lift Door Glass

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue of the Lift too close to the Lift Door glass

Applicable Vehicles

C2

Symptoms

Lift too close to the Lift Door Glass

Solution:

Upon Braun recommendation TBB has started adding shims under the 1000 lbs lift and also installing 10 bolts. TBB adding 4 shims 2 per side. Unit 1861576 body number the first unit for this installation. Install per diagram TBB 206862 or TBB 207033 depending on your application

Part number TBB 219150 Shim