



Replace Rear Door Outer Belt Seals

Classification	Repair Bulletin	Section/Group	11 - Closures	Country/Region	North America, EMEA, APAC
Year	2016 - 2018	Model	Model X	Version	All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

Certain Model X vehicles are equipped with rear door outer belt seals that could allow water to enter the rear door, potentially damaging components integral to automated door latching operation. If a component fails, manual door latching operation is not affected.

Correction

If diagnosis confirms that water ingress has affected rear door latching operation, perform the procedure described in this bulletin and all other procedures described in [SB-18-11-004](#), "Water Ingress into Rear Doors in Wet Climates."

Correction Description	Correction	Time
SB-18-11-007 Not Applicable	S011811007	0.00
Replace LH and RH rear door outer belt seals	S021811007	0.15

Required Part(s):	Part Number	Description	Quantity
	1098685-00-C	OUTER BELT SEAL PHANTOM ASS'Y,LH RR	1
	1098686-00-C	OUTER BELT SEAL PHANTOM ASS'Y,RH RR	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Procedure

Replace the LH and RH rear door outer belt seals (refer to Service Manual procedure 11704402).

Affected VIN(s) Affected Model X vehicles built before August 11, 2018.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.

