



Preliminary Information

PIT5642 Heated Seat Switch Indicators Inoperative or 110v Power Receptacle Switch Indicator Dimly Lit

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	Heated Seats RPO KA1/KQV or 110v Cargo Power Receptacle RPO KC9
Condition	Some customers may comment that the heated seat switch indicators are inoperative or very dim. Also, on trucks equipped with the cargo power receptacle, the green indicator in the switch is dimly lit. These concerns are only noticed if the interior lamp dimmer switch is set to a very low setting. If the interior lamp dimmer switch is adjusted to a higher setting, the issues will no longer be present.
Cause	The cause of these concerns is being investigated by engineering.

Correction:

At this time, no repairs should be performed. If the interior lamp dimmer switch is adjusted to a higher setting, the concern(s) will go away. If/When a repair is available, this PI will be converted to a bulletin.

Version History

Version	1
Modified	11/15/2018 - Created on

