

Published date: 11/19/2018

Preliminary Information

PIP5387D LGW Turbocharger Replacement Restriction has ended

Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions.
Cadillac	СТ6	2018	ALL	ALL	3.0 LGW	ALL

<u>Supersession Statement</u>

This PI was superseded to updated to end the restriction, please discard all copies of PIP5387C

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

General Motors, as part of our continued quality and improvement objective issued a part restriction through GM Technical Assistance on the turbochargers for the Cadillac CT6 with the 3.0L LGW engine.

That restriction has now ended. We want to take this opportunity to thank all the dealers that were involved in this restriction for their assistance.

Going forward please order the turbochargers through normal parts channels.

Recommendations / Instructions

Parts Information

Part Number	Part Description		
12696461	Right (B1) Turbocharger Assembly		
12696460	Left (B2) Turbocharger Assembly		

Warranty Information

Labor Operation	Description	Labor Time
4068290	Turbocharger Replace	Use Published Labor Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

















GENERAL MOTORS

© 2018 General Motors. All Rights Reserved.