



Preliminary Information

PIC6214C Antenna Missing During PDI

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore	2016 - 2019	All	All	All	All
Chevrolet	Trax	2016 - 2019	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	N/A
Condition:	Dealers are unable to locate antenna during PDI
Cause:	PDI does not show location of the antenna

Correction:

Antenna is located in the LH trim pocket in the trunk.



Version History

Version	4
Modified	09/01/2016 - Created on 02/24/2017-Updated Models 06/27/2017- Updated Model years 11/20/2018- Updated Model years

