



Bulletin No.: PIC6190A  
Published date: 11/28/2018

## Preliminary Information

### PIC6190A Foam And Cardboard Insert Found In Trunk During PDI Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2019	All	All	L3A	MKV


### Supersession Statement

This PI was superseded to update Model Years. Please discard PIC6190

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition / Concern

**When performing a pre-delivery inspection you may find a piece of foam that is surrounded by a cardboard shell that is found in the vehicle during PDI. ( See Photos below )**





### Recommendations / Instructions

**This Insert is a spacer that is part of the tire Inflator kit and should be placed between the compressor assembly and the tire sealant canister. This Insert needs to be installed to prevent the damage to the contents of the bag when tightening the hold down for the Inflator kit.**



Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

