



Preliminary Information

PIT5644 Temperature Gauge Fluctuation or Perceived Overheat Condition

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2015 - 2019	All	All	2.5L (LCV)	All
GMC	Canyon	2015 - 2019	All	All	2.5L (LCV)	All

Involved Region or Country:	North America
Condition:	The customer may note a fluctuation in the temperature gauge or a higher than expected gauge reading and perceived overheat condition.
Cause:	This condition is caused by air in the cooling system. Engineering is currently working to release a new coolant bottle to correct this concern, then this will be turned into a bulletin.

Version History

Version	1
Modified	11/27/2018 - Created



GENERAL MOTORS