




**HYUNDAI**  
**Technical Service Bulletin**

GROUP <b>BODY ELECTRICAL</b>	NUMBER <b>18-BE-015-1</b>
DATE <b>NOVEMBER, 2018</b>	MODEL(S) <b>Tucson (TL) Elantra GT (PD)</b>

**SUBJECT:** SOUND FADER SETTINGS CHANGE

This TSB supersedes TSB# 18-BE-015 to modify the Parts Information section and updates step 5 with additional information.

**Description:** This bulletin describes the procedure to determine if the vehicle's Radio Assembly /Navigation unit needs to be replaced as a result of the sound fader settings changing without any user input intermittently.

SYMPTOM(S)	
<b>Sound Fader Setting Change Without Any User Input</b>	
	

**Parts Information:**

Part Name	Part #
TL – Head Unit Assy - AVN	96560-D33504X
TL – Audio Assy	96160-D31004X
PD – Head Unit Assy - AVN	96560-G3061PMP
PD – Audio Assy	96160-G3300PMP


**Applicable Vehicles:**

- 18MY Tucson (TL)
- 18MY Elantra GT (PD)


**Warranty Information:** Normal warranty applies where applicable.

**Service Procedure:**


1. Start the vehicle by using the key (A), or with the Start Stop Button (A).




2. From the Home screen, select "All Menus" (B).



3. In the "All Menus" screen, select "Setup" (C).




4. From the "Setup" menu, select "Sound" (D).



5. Confirm fader settings have changed without any user input.

**If yes, replace the Radio Assembly/Navigation Unit.**



**NOTICE**

For vehicles with mileage **below 500 miles, order a new radio.**  
*Part number examples are listed in the table on page 1.*

For vehicles with mileage **above 500 miles, order a remanufactured radio.**  
*Remanufactured radio Part numbers have FLT or FL at the end.*

