



GROUP
BOD

MODEL
2018MY
Niro (DE HEV)

NUMBER
180 (Rev 1, 1/25/2018)

DATE
December 2017

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: FUEL FILLER DOOR
SPRING REPAIR (SA326)

* NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black background.

This bulletin provides the procedure to repair the fuel filler door pop up spring on all 2018MY Niro (DE) vehicles, produced from July 24, 2017 to December 7, 2017 which may not allow the fuel filler door to open properly. Kia's request for the completion of this Service Action on all affected vehicles in dealer stock, prior to delivery. Before conducting the procedure, verify that the vehicle is included on the list of affected VINs.



* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA326.

File Under: <Body>

Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair