



GROUP
ENG

MODEL
2018MY
Stinger (CK)

NUMBER
182



DATE
December 2017

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: EMISSIONS LABEL
REPLACEMENT (SA324)

This bulletin provides the procedure to replace the Emissions Label on some 2018MY Stinger (CK) vehicles equipped with Theta 2.0-T engines, produced from September 29, 2017 through November 20, 2017, which contains incorrect emissions information on both RWD and AWD models. Follow the procedure outlined in this bulletin to replace the new revised emissions label. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.

**ENG182/SA324
CLOSED. REFER TO
TSB SC152**



* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA324.

File Under: <Engine>

- Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair