

## Display of suspension setting in head unit implausible

---

Topic number	LI54.30-P-068430
Version	1
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	07-19-2018
Validity	213.#88 / #89 from modification year 17/2 to modification year 18/1
Reason for change	
Reason for block	

---

### Complaint:

Display of suspension setting in head unit does not match actual suspension setting, the display in the switch is correct

### Cause:

Air Body Control (SPC) control unit software

### Remedy:

Update software for Air Body Control (SPC) control unit using Xentry as of version 05/18

<b>Symptoms</b>
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Faulty display