



LTB01217NAS1

# TECHNICAL BULLETIN

13 NOV 2018

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

## INFORMATION

## SECTION:

310-01

## SUBJECT/CONCERN:

Fuel Tank Heatshield Corrosion

## AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:
Discovery Sport (LC)	2015 Onwards	500001 Onwards
Range Rover Evoque (LV)	2012 Onwards	000001 Onwards

**MARKETS:**

NORTH AMERICA

**CONDITION SUMMARY:****SITUATION:**

Corrosion may be visible on the fuel tank heatshield.

**CAUSE:**

This may be caused by the surface coating on steel heatshield being insufficient to prevent corrosion.

**ACTION:**

Should a customer express this concern, follow the Workshop Procedure below.

**PARTS:**

PART NUMBER	DESCRIPTION	QUANTITY
LR122799	Heatshield - Discovery Sport	1
LR122804	Heatshield - Range Rover Evoque	1
LR023457	Differential bolt(s)	2
LR001193	Rear driveshaft bolt(s)	6
LR001193	Front driveshaft bolt(s)	6

**TOOLS:**

Refer to Workshop Manual for any required special tools.

**WARRANTY:** **NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Heatshield - Fuel tank - Renew - Discovery Sport (GTDi 2.0L Petrol; without Active driveline)	19.55.03	1.5	05	LR060833
Heatshield - Fuel tank - Renew - Discovery Sport (GTDi 2.0L Petrol; with Active driveline)	19.55.03.34	1.8	05	LR060833
Heatshield - Fuel tank - Renew - Discovery Sport (Ingenium I4 2.0L Petrol)	19.55.03	1.8	05	LR076312
Heatshield - Fuel tank - Renew - Range Rover Evoque (GTDi 2.0L Petrol)	19.55.03	1.9	05	LR025815/LR041435
Heatshield - Fuel tank - Renew - Range Rover Evoque (Ingenium I4 2.0L Petrol)	19.55.03	1.9	05	LR041435

 **NOTE:**

Normal Warranty procedures apply.

**SERVICE INSTRUCTION:**

- 1 Renew fuel tank heatshield (see TOPIx Workshop Manual section 310-01: Fuel Tank and Lines - Removal and Installation - Fuel Tank Heatshield).