

Subject

**Ignition Switch Difficult to Turn**

Market

**USA**

Service Category

**Engine/Hybrid System**

Section

**Starting**

Applicability

**2016-2017 Camry MY Camry****APPLICABLE VEHICLES**

2016-2017

Camry

**CONDITION**

Some 2016-2017 model year Camry vehicles may experience an ignition switch that is difficult to turn from the lock to the accessory position.

**RECOMMENDATIONS**

Currently under investigation

If the condition of your vehicle matches the condition described on this document, create a TAS case and contact TAS and provide details prior to the repair. If it's a weekend or holiday continue with diagnosis and repair, save all parts and details, contact TAS on the next available work day and review details with TAS engineer.

**LINK REFERENCES**

This Tech Tip does not contain any link references