

Subject <b>Squeak Noise From Front of Vehicle On Uneven Surfaces - NO.1 Body Mount</b>		Market <b>USA</b>
Service Category <b>Suspension</b>	Section <b>Front Suspension</b>	
Applicability <b>16-18MY Tacoma16-18 MY Tacoma</b>		

**APPLICABLE VEHICLES**

<b>2016-2018</b>	<b>Tacoma</b>
------------------	---------------

**CONDITION**

Some vehicles may exhibit a squeak or rattle noise from the FR RH Body Mount Bushing when driving over uneven roads or bumps. Make sure to confirm that noise is coming from RH FR (No.1) Body Mount Bushing before proceeding.



Location of RH No.1 Body Mount

**RECOMMENDATIONS**

After confirming the noise from front RH No.1 Body Mount, submit the following information in a DPR:

1. BEFORE uninstalling the bolt from No.1 Body Mount, take a photo of the bushing condition and position in relation to the frame.



Example of bushing condition photo

Subject

**Squeak Noise From Front of Vehicle On Uneven Surfaces - NO.1 Body Mount**

Market

USA

Applicability

**RECOMMENDATIONS**

2. After the bolt is removed, take a photo of the bolt witness mark to the body and note the direction of the offset. (see below for detail)



**Location of Bolt top mounting surface and witness mark example**

**LINK REFERENCES**

This Tech Tip does not contain any link references