

SSM 47677

2018-2019 EcoSport vehicles equipped with power windows may exhibit a loss of power window functionality after multiple rapid switch operations. This may be due the power window thermal protection feature, which makes the switch inoperable for a short period. This is a normal characteristic and no repairs should be attempted. Normal switch functionality should be restored after the window motors have cooled down.