



Repair Notice

45-059

Section

45 - Engine Chassis Harness

Description

Air Dryer Pressure Ground Signal Fault Codes

Release Date

11/8/2018

Revision History

11/26/2018 - Updated part number to CN11750

Introduction

Peterbilt has determined that vehicle Models 365, 367, and 389 were manufactured with a Model Year 2018 PACCAR MX engine may have improper grounding from the air dryer pressure ground signal. The improper grounding creates faults and signal noise. DTC P1115 may set.

Resolution

CAMPAIGN

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
 2. If you are not using SmartLINK Service Management to start repair orders, review the DWWC or SIR for "Complete" next to the "45059" campaign code prior to performing this repair.
 3. Follow the procedures below to install a jumper to correctly ground the signals.
-

Warranty

Through Standard Warranty or for repairs completed by 12/01/2019, whichever is greater, Peterbilt will pay for parts

at dealer net plus applicable mark-up and labor:

- 0.3 hours labor to install the new ground jumper. Use Quick Claim Code 45059.
- File an additional claim for extraordinary circumstances, referencing 45059 in the CCC. A quick claim for standard labor must be filed first.
- Direct Fleets and Dealer Sponsored Fleets (DSF) may not use quick claims when submitting for repairs on chassis related to this bulletin but must submit a long form specifying part numbers, quantities, and pricing for parts used in the repair. Submittal of a Quick Claim for repairs made by the Fleet will be denied as pricing is incorrect on quick claims.

<i>For Field...</i>	<i>Enter...</i>
<i>Failure Location</i>	<i>045-002-074</i>
<i>Failure Type</i>	<i>700</i>
<i>Claim Type</i>	<i>C</i>
<i>Responsibility</i>	<i>09</i>
<i>SRT 045-A10</i>	<i>0.3 hours labor to install a new jumper harness</i>

Take off parts disposition: Scrap all take off parts 30 days after claim is paid

Parts

Parts are available at PACCAR Parts.

PART NUMBER	DESCRIPTION	QTY
A92-6018-2500	Overlay harness	1
CN11750	Chassis harness end cap	1
CN50300	Connector plug	3
	zip tie straps	As needed

Procedure

Procedure:

[45-059 Air Dryer Pressure Sensor Overlay Harness Procedure](#)

Attachments

[45-059 Chassis List](#)

[45-059 Customer Letter](#)

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2018 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).