



ERRONEOUS FAULT 1F2505 IS STORED IN THE DME

MODEL

G05 (X5 xDrive 50i)

With one or more of the following options equipped:

- 05AT - Driving Assistant Plus
- 05AU - Driving Assistant Professional
- 05DF - Active cruise control and STOP & GO function
- 05DL - Surround View
- 05DM - Parking Assistant
- 05DN - Parking Assistant Plus
- 05DV - Parking Assistant

SITUATION

The following fault is erroneously store in the Digital Motor Electronics (DME).

- FC **1F2505** – DME, encoding: Self-detection components implausible.

This fault does not cause any drivability complaints or engine warning lamps. This fault is normally detected during unrelated work

CAUSE

An error in the DME software.

CORRECTION

The erroneous fault should be ignored until it is corrected in a future software level.

PROCEDURE

If the affected vehicle is below the integration level below, disregard the erroneous fault.

Model	Integration Level
G05 (X5 xDrive 50i)	S18A-19-07-500 and higher

If the vehicle integration level is on a higher software level, perform diagnostics with ISTA Next.

WARRANTY INFORMATION

Not applicable

[Copyright ©2018 BMW of North America, Inc.]