

Technical Service Bulletin

SUBJECT:			No:	TSB-18-27-001
TORQUE UPDATES: UNITS OF TIGHTENING TORQUE & NUMERICAL VALUE FOR REAR AXLE - SERVICE MANUAL REVISION			DATE:	December 2018
			MODEL: 2008-2014 Lancer Evolution	
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER		[X] TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCESS	OR	[] SALES MANAGER

PURPOSE

This TSB updates the Rear Axle section of the affected Service Manuals to correct the tightening torque for the Differential Carrier Assembly.

AFFECTED VEHICLES

• 2008 - 2014 Lancer Evolution

AFFECTED SERVICE MANUAL

• 2008-2014 Lancer Evolution Service Manual, Group 27 - Rear Axle

Please make the indicated changes to the 2008 - 2014 Lancer Evolution Service Manual, Group 27 - Rear Axle -> Differential Carrier Assembly -> Removal and Installation.

REMOVAL AND INSTALLATION

A CAUTION

• The part indicated by ^{*} is the bolt with friction coefficient stabilizer. In removal, ensure there is no damage, clean dust and soiling from the bearing and thread surfaces, and tighten them to the specified torque.

