

Technical Service Bulletin

SUBJECT: UPDATES TO HOOD LATCH MOUNTING BOLT & TIGHTENING TORQUE - SERVICE MANUAL REVISION			No:	TSB-18-42A-004
			DATE:	December 2018
			MODEL: See below	
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER		[X] TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCESSOR		[] SALES MANAGER

PURPOSE

This TSB updates the Body section of the affected Service Manuals to add the type of the hood latch mounting bolts and to correct the tightening torque for the hood.

AFFECTED VEHICLES


- 2014 2019 Outlander
- 2011 2018 Outlander Sport
- 2018 Outlander PHEV
- 2018 Eclipse Cross

AFFECTED SERVICE MANUAL


- 2014 2019 Outlander Service Manual, Group 42 Body
- 2011 2018 Outlander Sport Service Manual, Group 42 Body
- 2018 Outlander PHEV Service Manual, Group 42 Body
- 2018 Eclipse Cross Service Manual, Group 42 Body

Copyright 2018, Mitsubishi Motors North America, Inc.

Please make the indicated changes to the 2014 - 2019 Outlander, 2011 - 2018 Outlander Sport, 2018 Outlander PHEV Service Manual, Group 42 - Body -> Body ->Hood -> Adjustment of Hood Level and Hood Striker Engagement.



- Loosen the hood latch mounting bolts but do not remove them. Move the hood latch up/down and left/right to align the hood level and adjust the hood striker engagement.
- 3. After the adjustment, tighten the hood latch mounting bolts to 9.0 ± 1.0 Nm (80 ± 8 in-lb).



Please make the indicated changes to the 2014 - 2019 Outlander, 2011 - 2018 Outlander Sport, 2018 Outlander PHEV Service Manual, Group 42 - Body -> Hood -> Removal and Installation.

