#### NISSAN NORTH AMERICA, INC Copyright ©



# SERVICE BULLETIN Classification: Reference: Date: EL18-038 NTB18-085 December 13, 2018

# 2018 TITAN CREW CAB AND TITAN XD CREW CAB; RUNNING BOARD LIGHT COVERED

**APPLIED VEHICLES:** 2018 Titan (A61)

2018 Titan XD (A61)

**APPLIED BODY:** Crew Cab

**APPLIED SYSTEM:** Dealer or Vehicle Processing Center (VPC) installed running board

lighting kit

#### IF YOU CONFIRM

The running board light near the middle of one or both running boards does not appear to light up (see Figures 1 and 2 on the next page)

### **And**

The hole in the running board's reinforcement bracket does not line up with the running board light (the light is covered).

## **ACTION**

Replace the running board on the side of the vehicle where the running board light does not appear to be lit up.

- See PARTS INFORMATION to select the correct part.
- For instructions on how to replace the running board(s), refer to ASIST > Model
   Titan > Year 2018. Select the Acc. Install Instructions tab, and then scroll down
   and select Running Board\_Titan\_999T6 W3xxx.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.




Figure 1




Figure 2

2/3 NTB18-085

### **PARTS INFORMATION**

MODEL	DESCRIPTION	PART NUMBER	QUANTITY
2018 Titan Crew Cab and Titan XD Crew Cab	RUNNING BRD <b>LH</b> CC 6.5 W/LIGHTS CHR ( <b>bright chrome</b> )	999T6-W3600	1 *
	RUNNING BRD <b>RH</b> CC 6.5 W/LIGHTS CHR ( <b>bright chrome</b> )	999T6-W3601	1 *
	RUNNING BRD <b>LH</b> CC 6.5 W/LIGHTS DK CHR ( <b>dark</b> <b>chrome</b> )	999T6-W3704	1 *
	RUNNING BRD <b>RH</b> CC 6.5 W/LIGHTS DK CHR ( <b>dark</b> <b>chrome</b> )	999T6-W3705	1 *

<sup>\*</sup> Order and replace only the LH and/or RH sides as needed.

### **CLAIMS INFORMATION**

## Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
R&I One Running Board	(1)	YA70AA	ZE	32	(2)

<sup>(1)</sup> Reference the Parts Information table above, and use the Running Board as the Primary Failed Part (PFP).

### **AMENDMENT HISTORY**

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 13, 2018	NTB18-085	Original bulletin published.

3/3

NTB18-085

<sup>(2)</sup> Reference the current Nissan Warranty Flat Rate Manual and use the indicated Flat Rate Time (FRT).