
Reference	SSM74188
Models	Range Rover Velar / L560
Title	Roof Opening Panel - Low Level Service Repair
Category	Body
Last modified	11-Dec-2018 00:00:00
Symptom	105000 Roof Options

Content

Issue:

Customers may report one or more of the following issues with the roof opening mechanism

- Jammed.
- When opening in tilt only one side opens.
- Rattles from guide rails or mechanism.

Cause:

Defective roof opening panel guide rails

Action:

Do not order a complete panoramic roof frame.

Jaguar Engineering have released a low level service repair for any of the above symptoms.

Please refer to Topix, section 501-17 Roof Opening Panel, Removal and Installation - Roof Opening Panel Guide Rails

Range Rover Velar Service Part Numbers:-

Left Hand Guide Rail = LR122588

Right Hand Guide Rail = LR122587

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.