

Subject Missing 35 MPa O-ringMPa O-ring		Market USA
Service Category Engine/Hybrid System	Section Fuel System	
Applicability 2016-2020 Toyota Mirai		

APPLICABLE VEHICLES	
2016-2020	Mirai

CONDITION
Some 2016-2020 model year Mirai vehicles might encounter fueling issues which may result in the loss of the 35 MPa O-ring.

RECOMMENDATIONS
During any service of the Mirai, please inspect the fueling receptacle for the presence of the 35 MPa O-ring. The following photos have been provided to assist in identification.



Example of vehicle Missing 35 MPa O-ring

Example of vehicle with 35 MPa O-ring present

If the vehicle matches the condition, create a TAS case and contact TAS and provide details prior to the repair. If it's a Sunday or holiday, continue with diagnosis and repair, save all parts and details, contact TAS on the next available work day and review details with TAS engineer.

LINK REFERENCES
This Tech Tip does not contain any link references