



Countries:	CANADA, UNITED STATES, MEXICO	Document ID:	IK1201427
Availability:	ISIS, NotSIR	Revision:	0
Major System:	ENGINES	Created:	12/5/2018
Current Language:	English	Last Modified:	12/5/2018
Other Languages:	NONE	Author:	Bobby Christopher
Viewed:	67		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 1	 0

Title: Incorrect Lubricating Oil Dipstick: International® WorkStar®

Applies To: .SL9 CM2350 L101 •2016 WorkStar® High Hood Non-AWD •2017 WorkStar® High Hood Non-AWD

Change Log

Please refer to the change log text box below for recent changes to this article:

12/05/2018 - Initial Article Release.

Description

Incorrect Lubricating Oil Dipstick: International® WorkStar®

Symptoms

Diagnostic Trouble Codes & Dashboard Indicator Lights:

DTC/Light	Description
No Faults or Warning Lights	

Customer Observations or Concerns:

- lubricating oil level will appear $\frac{3}{4}$ in to 1 in above FULL marking on lubricating oil dipstick
-

Special Tools / Software

Tool Description	Tool Number	Comments	Instructions
Not Applicable			

Service Parts Information

Kit Description	Part Number	Quantity Required	Notes
Oil Dipstick	5526197	1	

Diagnostic Steps

See Cummins TSB

Quickserve Link: [TSB180165](#)

Repair Step(s)

See Cummins TSB

Quickserve Link: [TSB180165](#)

Warranty Information**Warranty Claim Coding:**

Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.

Standard Repair Time(s):

Refer to the [SRT Manual](#) for Repair Times

Other Resources

[Cummins Quickserve Home](#)

[Master Service Information Site](#)



Hide Details

Feedback Information

Viewed: 66

Helpful: 1

Not Helpful: 0

No Feedback Found

Copyright © 2019 Navistar, Inc.