



Replace Trunk Seal To Ease Closure

Classification	Repair Bulletin	Section/Group	11 - Closures	Country/Region	United States, Canada
Year	2017, 2018	Model	Model 3	Version	All

Bulletin Classification: This repair bulletin provides instructions and guidelines for a noted condition or a customer concern. The information provided can address a broad range of known or perceived issues with the operation of Tesla vehicles. This bulletin might not be VIN-specific. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

Condition

For some Model 3 vehicles, the trunk lid might require more effort than expected to fully close.

Correction

Upon customer complaint of extra effort to fully close the trunk lid, replace the trunk seal with an updated part.

Correction Description	Correction	Time
SB-18-11-009 Not Applicable	S011811009	0.0
Replace Trunk Seal With Updated Part	S021811009	0.15

Required Part(s):	Part Number	Description	Quantity
	1091069-00-C	M3, Seals, Trunk, Decklid	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Procedure

Replace the trunk seal (refer to Service Manual procedure 11702002).

Affected VIN(s) Affected Model 3 vehicles built before approximately March 26, 2018.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.