



Technical Tip

Topic	91-18-17TT - No Rear USB Port Operation
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	December 7, 2018

Condition

ATTENTION:

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Rear USB Port Inoperable

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2018	All	All	All	All

Technical Background

No operation from rear USB port.

Service

Before replacing parts for rear USB concerns, check the vehicle's PR code list.

- The vehicle may have a trim level with USB installed with no operation.
- If vehicle has PR code UI5 it has only one USB port.
- For vehicles with 2 USB ports it will have UQ4.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2053224/1	12/7/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.