



Technical Tip

Topic	91-18-18TT - Horn Inoperative, Steering Wheel Controls Inoperative U108E and or U0212
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	December 14, 2018

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Horn Inoperative, Steering Wheel Controls Inoperative U108E and or U0212

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (Except Routan)	2010-2018	All	All	All	All

Technical Background

DTC	Description
U108E00	Control unit in steering wheel No Communication
U021200	Lost Communication With Steering Column Control Module

Service

These faults indicate no communication with the **-J453-** Multifunction Steering Wheel Control Module and or **-E221-** Control Unit in Steering Wheel on left side steering wheel controls.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2053314/1	12/14/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.