



Technical Tip

Topic	96-18-05TT - C1190F6: Blind Spot Recognition Control Module 2 - J1087 - Incorrect Version Installed
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	December 14, 2018

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

C1190F6: Blind Spot Recognition Control Module 2 -J1087- Incorrect Version Installed

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas, Tiguan LWB, Golf/GTI, Golf R, Golf Sportwagon	2018	All	All	All	All

Technical Background

This fault may set if one of the Blind Spot Detection Control Module's -**J1086**- or -**J1087**- had been replaced and now the software version numbers do not match.

Service

Update the modules following the information from:

Atlas: TB 2051570 (96-18-04)

Tiguan LWB: TB 2051421 (96-18-08)

Golf/GTI, Golf R, Golf Sportwagon, Alltrack: TB 2052500 (96-18-07)

Clear the faults and reevaluate the operation of the system.



Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2053313/1	12/14/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.