



Subject: DRW18 - MAZDA3 - C-BCM & VCM - SOFTWARE CONCERN	∴
	Last Issued: 12/14/2018

DESCRIPTION

1) Center Body Control Module (C-BCM) software concern

The average fuel economy may not be calculated / indicated correctly.

2) Vehicle Control Module (VCM) software concern

- The Smart Brake Support (SBS) OFF indicator light may turn on.
- The personalization menus of i-ACTIVESENSE may not be displayed in the center display.

Causal factor: Inappropriate software of C-BCM and VCM.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.