

QUARANTINE NOTICE

Reference number:	QN-17-1167	Issued: 23 November, 2018
Subject:	Headlamp Function Check	
Model(s):	Vantage 19MY	
VIN range:	Refer to the separately published list of Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Note: *This repair is the same as Service Action SA-17-1167. Use this Quarantine Notice for vehicles that are not registered and have not been given to a Customer.*

Some vehicles in the affected VIN list for this Quarantine Notice may now be registered and given to a Customer. Make sure that you do a check of the Online Dealer Warranty (ODW) database to make sure that all necessary work is done to every vehicle.

Reason for this Quarantine Notice

Aston Martin has found a problem with the headlamps on some Vantage 19MY vehicles. Do the procedure that follows to make sure the headlamps operate correctly.

Note: *This Quarantine Notice forms part of SPL-00-1180 - Vantage 19MY Customer Satisfaction Campaign.*

Of the checks included in the Customer Satisfaction Campaign, the one in this Quarantine Notice must be started first.

Workshop Procedure

1. Connect the vehicle to a charging pack.
2. Turn the headlamps on ('dipped' setting) and keep them on for 15 minutes.
Note: *If other Quarantine Notice checks are to be done on the vehicle, keep the headlamps on until they are completed.*
3. If the headlamps operate correctly, no more steps are required. If a headlamp did not stay illuminated, go to Step 4.

Note: *Step 4 must only be done if a headlamp does not operate correctly.*

4. Replace the headlamp (refer to Workshop Manual Procedure 17.01.AB or 17.01.BB).
5. Submit an EPDR form.

Part Data

Description	Part Number	Quantity
HEADLAMP ASSEMBLY, LH (RHD)	KY63-13W030-AD	1
HEADLAMP ASSEMBLY, LH (LHD)	KY63-13W030-BD	1
HEADLAMP ASSEMBLY, LH (Federal)	KY63-13W030-CD	1
HEADLAMP ASSEMBLY, RH (RHD)	KY63-13W029-AD	1
HEADLAMP ASSEMBLY, RH (LHD)	KY63-13W029-BD	1
HEADLAMP ASSEMBLY, RH (Federal)	KY63-13W029-CD	1

Warranty Data

Procedure and Labour Time

Tier A

Description	Labour Time
Right Side Headlamp Assembly, RHD – Inspect only	0.25 hours
Right Side Headlamp Assembly, RHD – Inspect and repair	1.3 hours

Tier B

Description	Labour Time
Right Side Headlamp Assembly, LHD – Inspect only	0.25 hours
Right Side Headlamp Assembly, LHD – Inspect and repair	1.3 hours

Tier C

Description	Labour Time
Left Side Headlamp Assembly, RHD – Inspect only	0.25 hours
Left Side Headlamp Assembly, RHD – Inspect and repair	1.3 hours

Tier D

Description	Labour Time
Left Side Headlamp Assembly, LHD – Inspect only	0.25 hours
Left Side Headlamp Assembly, LHD – Inspect and repair	1.3 hours

Tier E

Description	Labour Time
Left and Right Side Headlamp Assembly, RHD – Inspect only	0.25 hours
Left and Right Side Headlamp Assembly, RHD – Inspect and repair	2.2 hours

Tier F

Description	Labour Time
Left and Right Side Headlamp Assembly, LHD – Inspect only	0.25 hours
Left and Right Side Headlamp Assembly, LHD – Inspect and repair	2.2 hours

Tier G

Description	Labour Time
Right Side Headlamp Assembly, Federal – Inspect only	0.25 hours
Right Side Headlamp Assembly, Federal – Inspect and repair	1.3 hours

Tier H

Description	Labour Time
Left Side Headlamp Assembly, Federal – Inspect only	0.25 hours
Left Side Headlamp Assembly, Federal – Inspect and repair	1.3 hours

Tier J

Description	Labour Time
Left and Right Side Headlamp Assembly, Federal – Inspect only	0.25 hours
Left and Right Side Headlamp Assembly, Federal – Inspect and repair	2.2 hours

If you have any questions related to this Quarantine Notice, please contact: Aston Martin Technical Services on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
Or contact your After Sales Manager.

The English version of this Quarantine Notice is written in Simplified Technical English to ASD-STE100™.