



Preliminary Information

PIP5284A P0496 after performing Strategy Based Diagnostics

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Trax	2013 - 2019	All	All	1.4 LUJ LUV	All
Buick	Encore	2013 - 2019	All	All	1.4 LUJ LUV	All

Supersession Statement

This PI was Superseded to Update Model Years. Please Discard PIP5284.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Vehicle continues to set DTC P0496 after you have completed Strategy Based Diagnostics.

Recommendations / Instructions

Contact GM TAC if you have a 2013-2019 Chevrolet Trax or Buick Encore that continues to set DTC P0496 after you have completed Strategy Based Diagnostics

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS