



Preliminary Information

PIP5616 2019 GF9 9T45 9T50 9T60 9T65 Input Speed Sensor And/Or Intermediate Speed Sensor DTCs P0717 P07BF P07C0 P176C P176D

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2019	ALL	ALL	ALL	M3W
Buick	Envision	2019	ALL	ALL	ALL	M3T
Buick	LaCrosse	2019	ALL	ALL	ALL	M3G
Buick	Regal	2019	ALL	ALL	ALL	M3D, M3T
Cadillac	XT4	2019	ALL	ALL	ALL	M3H
Chevrolet	Blazer	2019	ALL	ALL	ALL	M3D, M3V
Chevrolet	Cruze	2019	ALL	ALL	ALL	M3D
Chevrolet	Equinox	2019	ALL	ALL	ALL	M3D
Chevrolet	Malibu	2019	ALL	ALL	ALL	M3E
Chevrolet	Traverse	2019	ALL	ALL	ALL	M3V
GMC	Terrain	2019	ALL	ALL	ALL	M3H, M3U

Involved Region or Country	North America and NA Exports
Condition	Intermittent Input Speed Sensor and/or Intermediate Speed Sensors electrical DTCs, P0717, P07BF, P07C0, P176C, P176D, on 2019 vehicles equipped with a GF9, 9TXX transmission assembly.
Cause	Possible open in the Input Speed Sensor.

Correction:

If normal SI diagnostics does not lead to a resolution, replace the Input Speed Sensor.

Note : This concern is still being investigated and will be updated or advanced to a TSB, if needed.

Version History

Version	1
Modified	12/20/2018 - Created on



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.