
TIS Service Bulletin Page 1 of 1



February 2019 Technical Service

## DELIVERY STOP: REPLACE DYNAMIC STABILITY CONTROL (DSC) HYDRAULIC UNIT

## **MODEL**

G01 (X3)

## **SITUATION**

A Delivery Stop has been issued (effective February 8, 2019) on Model Year 2019 BMW X3 SAV vehicles produced from February 2, 2019 – February 6, 2019. This delivery stop involves the DSC hydraulic unit which will need to be replaced.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired.

Do not use or sell replacement equipment/parts subject to a Delivery Stop.

Affected vehicles will show the campaign as "Open" when checked either in Warranty Vehicle Inquiry, AIR or ISPA Next. The affected vehicles will be identified with the description: **STOP013690 B340219 Delivery Stop: Dynamic Stability Control Hydraulic Unit** 

This bulletin will be updated with repair and warranty information when it becomes available.

[ Copyright ©2019 BMW of North America, Inc. ]