

1 12 02-18



Service Information Bulletin

SUBJECT	DATE
SPN 108	December 2018

Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0015	EPA07 MBE900	SPN 108/FMI 2	Code currently missing in PSL.

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
 Telephone: 313-592-5000
www.demanddetroit.com

28.1 SPN 108/FMI 2

The diagnosis is typically: Ambient Pressure Plausibility Fault (High Box).

1. If SPN 108/FMI 2 code is present, replace the Motor Control Module (MCM).