



Service Bulletin

File in Section: -

Bulletin No.: PIE0463A

Date: December, 2018

ENGINEERING INFORMATION

Subject: Engineering Information – Smoke or Burning Odor from Underhood with Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F or P058D

This PI has been revised to end the need for information from the field. Please discard PIE0463.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Impala	2014	2018			All	All
	Malibu						

If you encounter a vehicle with the above condition, refer to Bulletin 18-NA-367 for further diagnosis.

Version	2
Modified	Released April 30, 2018 December 21, 2018 – Ended the need for further information from the field.