



Service Bulletin

File in Section: -

Bulletin No.: 18-NA-023

Date: November, 2018


INFORMATION

Subject: Warped Driver Side Floor Liner in Accelerator Pedal Area

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Traverse	2018	2018			All	All

Involved Region or Country	North America and NA Export vehicles
Condition	Some technicians may comment on the new floor liners that are attempting to be installed on the vehicle are warped around the accelerator pedal location of the liner.
Cause	This may be due to the packaging of the liners may not provide sufficient support during transit.
Correction	Important: Do not install the warped liners in the vehicle. Return and re-order warped parts to ADI (US) or to the Service Warehouse (Canada) for part replacement through the Part Quality Return process. These returns then go to the CCRC for evaluation and action as required.

Example of Warped Liner



4944586

Example of Good Liner



4944588

Parts Information

Description	Part Number
MAT PKG-F/FLR *BLACK)(INSTA	84331850
MAT PKG-F/FLR *DARK ATMOSPHR	84331851

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
0520940	Floor Mat Package Replacement	Use Published Labor Operation Time

Version	2
Modified	Released January 23, 2018 Revised November 14, 2018 — Added Labor Operation

