



Technical Journal

TITLE:

SPA V60 Front windows initialization

| | | | |
|--|---|--|-----------------------------------|
| REF NO: TJ 34099.2.1 | ISSUING DEPARTMENT: Technical Service | CAR MARKET: United States and Canada | |
| PARTNER: 3 US 7510 Volvo Car USA | | ISSUE DATE: 2018-10-29 | STATUS DATE: 2018-11-05 |
| FUNC GROUP: 8350 | FUNC DESC: Window lift | Page 1 of 2 | |

“Right first time in Time”

Attachment

Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|----------|-------|------|------|-------|------------|-------|-----------------|------------------|
| 225 | | | | | | | 2019-2019 | 21 | 0000001-9999999 | 201817-209952 |

CSC Customer Symptom Codes

| Code | Description |
|------|--|
| SL | Electrical operated window/No/reduced/incorrect function |

VST Operation Number

| VST Operation Number | Description |
|----------------------|-------------------------------------|
| 36004-2 | Software control module downloading |

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

If the front windows can not be initialized, follow the advice under "Service".

SERVICE:

* Perform a total software upgrade according to TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8350.