



# Technical Journal

TITLE:

**Lumbar support, inflates when opening door**

REF NO:  
**TJ 34091.1.0**

ISSUING DEPARTMENT:  
**Technical Service**

CAR MARKET:  
**United States and Canada**

PARTNER:  
**3 US 7510 Volvo Car USA**

ISSUE DATE:  
**2018-11-16**

STATUS DATE:  
**2018-11-29**

FUNC GROUP:  
**8524**

FUNC DESC:  
**Backrest cushion**

**Page 1 of 2**

**“Right first time in Time”**

## Attachment

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2019		0000241-0001191	201835-201839
225							2019-2019		0000315-0016379	201817-210839
234							2017-2019		0000350-0616333	201617-201839
235							2017-2019		0000160-0095240	201624-201839
236							2018-2019		0000098-0075790	201746-201839
238							2018-2019		0000161-0099218	201641-201839
246							2018-2019		0000389-0266979	201717-201839
256							2016-2019		0000561-0454523	201505-201839

## CSC Customer Symptom Codes

Code	Description
TM	Front seat/Power seat adjustment/folding does not work
UO	Front seat/Automatic adjustment (memory) does not work

## VST Operation Number

## DTC Diagnostic Trouble Codes



## Text

### DESCRIPTION:

If lumbar support inflates when unlocking the car or when a door is opened, follow instructions under Service.

### SERVICE:

A new software with changed functionality has been introduced in week 40, 2018. Download a Total Upgrade in accordance with VIDA instructions and TJ 31543.

With the new software, the automatic adjustment of the lumbar support waits until the car is started (driver is sitting on the seat).

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8524.