



Technical Journal

TITLE:
POT opening does not work intermittent

REF NO: TJ 33565.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-03-06	STATUS DATE: 2018-03-12
FUNC GROUP: 8327	FUNC DESC: Door operation, electrical; door operati	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536							2019-2019		0000001-0999999	201746-201852

CSC Customer Symptom Codes

Code	Description
1K	Tailgate/trunk lid/Automatic opening/closing does not work
WJ	Tailgate/trunk lid/Hard to open

VST Operation Number

DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

*POT (Power Operated Tailgate)

Customer concern POT (Power operated tailgate) does not open all the time, follow advice under service.



SERVICE:

Do not replace the POT module, new software is planned to be released 18w17.

VEHICLE REPORT:

Yes, please submit a Vehicle Report "Support not needed", use function group 8327.