



Technical Journal

TITLE:
Unusual noise while driving from sealing ring

REF NO: TJ 33524.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-03-08	STATUS DATE: 2018-03-14
FUNC GROUP: 7731	FUNC DESC: Hub, front	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
1XX							2007-2018		0000850-0460656	200605-201748

CSC Customer Symptom Codes

Code	Description
C4	Complete vehicle/Unusual noise/While driving
D2	Front/rear axle/Unusual noise
X1	Suspension/Unusual noise

VST Operation Number

DTC Diagnostic Trouble Codes

Text

DESCRIPTION:

If customer experience unusual noise from front drive shaft, please follow advice under Service.

**SERVICE:**

If noise is confirmed, check first if the sealing ring is displaced, if so, proceed with replacement of the sealing ring according to VIDA.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 7731.