

SS: 1033979 TBB Main Harness wiring improvement

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the potential issue of the main harness rubbing against a support bracket over head at the T Break above/ behind the driver head.

Applicable Vehicles

C2

Symptoms

Components inop

Solution:

Adding Edge guard 3.5 inches (TBB 220956) to the bracket 178682.

Add the Edge trim to the right and left side of the unit. Sample diagram 179606.