

M272 or M273 Oil Filter Housing Leaking

Topic number	LI01.00-P-069058
Version	1
Function group	01.00 General
Date	11-19-2018
Validity	All Vehicles with M272 or M273 Engines
Reason for change	
Reason for block	

Complaint:

Oil leaking from filter housing on M272 or M273 engines.

Cause:

Potential failure of seal(s).

Remedy:

If housing is not physically damaged: Replace the appropriate seal utilizing the proper part number.

Please be sure to ensure part number is most up-to-date by utilizing EPC.

Symptoms
Power generation / Engine lubrication/oil cooling / Leakage / External oil loss
Power generation / Engine lubrication/oil cooling / Indicator lamp / Engine oil level indicator lamp / lit
Power generation / Engine lubrication/oil cooling / Display message / Oil sensor message
Power generation / Engine lubrication/oil cooling / Function / Oil level too low

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 272 184 02 80			Oil Cooler On Housing	1	Oil Cooler/Filter Housing Seal	X
A 272 184 00 80			Oil Filter To Timing Case	1	Oil Filter Housing To Timing Case Seal	X

Validity		
Vehicle	Engine	Transmission
*	272	*
*	273	*