



Technical Journal

TITLE:

Rear sun curtain, creaking noise

REF NO:	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-03-26	STATUS DATE: 2018-03-29
FUNC GROUP: 8516	FUNC DESC: upholstery for rear shelf; uphol- stery fo	Page 1 of 8	

“Right first time in Time”

Attachment

File Name	File Size
TJ 33492.pdf	1.5808 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
138							2016-9999		0000122-0999999	201345-999952

CSC Customer Symptom Codes

Code	Description
G4	Headlining/Unusual noise
WL	Cargo area cover/Unusual noise

VST Operation Number

VST Operation Number	Description
98707-2	Sunblind rear window adjust acc. to TJ33492

Text

DESCRIPTION:

If a creaking noise is heard when rising or lowering the rear sun curtain, follow instruction under Service.

**SERVICE:**

Remove two O-rings according to instruction "TJ 33492.pdf".

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8516.

To view TJ attachment continue to next page. This TJ has one attachment.