

WJ25 Campaign - Retrofitting Connect Functions (MY 2018 718)

English (GB)

- [Overview](#) on page 1
- [Porsche Mobility](#) on page 1
- [Parts required](#) on page 2
 - [Ordering required parts](#) on page 2
- [Warranty processing](#) on page 2
 - [Scope 1: Vehicles with Navigation system and with Voice control \(I-no. QH1\)](#) on page 2
 - [Scope 2 - 13: Vehicles without Navigation system \(I-no. 7Q0\) and without Voice control \(I-no. QH0\)](#) on page 3

WJ25 Campaign - Retrofitting Connect Functions

Overview

Vehicles with missing Connect functions were produced due to an allocation error during production.

As a result, the Connect functions are not available in these vehicles.

Since not all the Connect functions can be retrofitted, the cost of the Connect package that was originally ordered will be reimbursed. In addition, the MirrorLink function and an Apple® CarPlay-compatible USB interface in the centre console storage bin will be retrofitted on the vehicles.

Pease Note: This campaign affects only 1 vehicle for Puerto Rico. There are no U.S. vehicles affected.

Model type	718 (982)
Model year	2018
Manufacturing period	between 01/03/2018 and 04/06/2018
Number	1

To download a list of your affected customers for this campaign, please follow the instructions found at <https://ppn.porsche.com/portal/docs/DOC-182765>.

Porsche Mobility

If requested, the mobility of the affected customer can be guaranteed by offering a suitable replacement vehicle or by having the vehicle transported to the relevant Porsche Centre.

Please invoice this additional service with the campaign scope via WWS.

Parts required

Part No.	Designation	Quantity/vehicle	Parts return request*
00004399044	Retrofit kit for Apple® CarPlay	1 ea.	No

Also required for vehicles without Navigation system (I-no. 7Q0) and without Voice control (QH0):

Part No.	Designation	Quantity/vehicle	Parts return request*
9A703550401	GPS antenna	1 ea.	No
9P4979005	GPS antenna line	1 ea.	No
99951307640	Tie-wrap	10 ea.	No
95560683800	Tie-wrap with fixing clips	5 ea.	No
99950719540	Expanding spring, 10.7 x 26.4	1 ea.	No
N 90799102	Screw, M18 x 1.5 x 18	1 ea.	No
...	Steering-column switch (see Technical Information)	1 ea.	No

* The parts must be stored until such a time as the **related warranty or campaign claim has been credited** in WWS. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Ordering required parts

Please Note: Since only 1 vehicle affected, all required parts will be shipped directly to respective dealership.

Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1: Vehicles with Navigation system and with Voice control (I-no. QH1)

Damage code WJ25 66 000
 Repair code 1

Working time 342 TU

Scope 2 - 13: Vehicles without Navigation system (I-no. 7Q0) and without Voice control (I-no. QH0)

Please note that the part number of the required steering-column switch is different for scopes 2 to 13.

Damage code WJ25 66 000

Repair code 1

Working time 479 TU

If any questions arise, please feel free to contact me directly.

Brian McManaman
Senior Regulatory Affairs Consultant
brian.mcmanaman@porsche.us
770-290-3418